

CRACKLE & NÁCAR



187828 Crackle Decor Nieve
6,5×33 cm./2.6"×13" **M940**
8 mm. de espesor/thickness




187781 Crackle Decor Marfil
6,5×33 cm./2.6"×13" **M940**
8 mm. de espesor/thickness



187829 Crackle Decor Laguna
6,5×33 cm./2.6"×13" **M940**
8 mm. de espesor/thickness



187830 Crackle Decor Camelia
6,5×33 cm./2.6"×13" **M940**
8 mm. de espesor/thickness



187780 Crackle Decor Metal
6,5×33 cm./2.6"×13" **M977**
8 mm. de espesor/thickness



187831 Crackle Nieve
6,5×33 cm./2.6"×13" **M936**
8 mm. de espesor/thickness



187833 Crackle Marfil
6,5×33 cm./2.6"×13" **M936**
8 mm. de espesor/thickness



187832 Crackle Laguna
6,5×33 cm./2.6"×13" **M936**
8 mm. de espesor/thickness



187834 Crackle Camelia
6,5×33 cm./2.6"×13" **M936**
8 mm. de espesor/thickness



187779 Losanga Nacar
6,5×33 cm./2.6"×13" **M936**
8 mm. de espesor/thickness





187780 Crackle Decor Metal 6,5x33 cm./2.6"x13"



• • • •

•= Ok C = Consultar/Consult



187755 Lavabo Heller Duo 36x36x12 cm./14.2"x14.2"x4.7"

187830 Crackle Decor Camelia 6,5x33 cm./2.6"x13"

187834 Crackle Camelia 6,5x33 cm./2.6"x13"



• • • •

•= Ok C = Consultar/Consult